

HISTORIC AMERICAN ENGINEERING RECORD

HAER
COLO.
24-BHAWK,
1-

Index to Photographs

Gregory Tailings (Ruins)

HAER No. CO-39

Junction of Highways 269 and 119
Black Hawk
Gilpin County
Colorado

NOTE: Photographs were taken by Jim Johnson, photographer from Fototek,
February 10, 1987

- CO-39-1 VIEW OF TAILINGS, LOOKING UPSTREAM FROM SOUTH
- CO-39-2 VIEW OF SOUTH CRIB WALL AND TAILINGS
- CO-39-3 VIEW OF CENTER SECTION OF CRIB WALL AND TAILINGS
- CO-39-4 VIEW OF NORTH CRIB WALL AND TAILINGS
- CO-39-5 VIEW OF NORTH END OF TAILINGS
- CO-39-6 VIEW OF TAILINGS, LOOKING NORTH UPSTREAM FROM CENTER
- CO-39-7 DETAIL VIEW OF CORNER OF SOUTH CRIB WALL
- CO-39-8 DETAIL VIEW OF SOUTH CRIB WALL STRUCTURE
- CO-39-9 DETAIL VIEW OF CRIB LAMINATIONS IN BEST CONDITION
- CO-39-10 DETAIL VIEW OF CRIB LAMINATIONS IN WORST CONDITION
- CO-39-11 DETAIL VIEW OF COLLAPSED CRIB AND SEEPAGE
- CO-39-12 DETAIL VIEW OF LAMINATED AND UNLAMINATED CRIB WALL JUNCTION